

# Work Order ID 71075

Tuesday, June 21, 2011 3:46:40 PM



Page 1

Item ID: D412-702-105B

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 6/21/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/21/2011 Req'd Qty: 1.00



Customer:

Reference: disassemble

Approvals:

Process Plan: *W*

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

ICA-D412-702

3

110

0.00



Small Fab

Small Fab

Memo

0.00

PULL FROM STOCK:  
1 X D412-702-105B B65012  
DISASSEMBLE KIT  
RETURN TO STOCK:  
D3573-1 B57222  
D3579-046 B59040  
DISCARD ALL HARDWARE

*EF 11/06/22* (1)

130

Identify as per dwg & Stock Location: *8274*

0.00



Packaging

Packaging

Memo

0.00

RETURN PARTS TO STOCK USING ORIGINAL B/N

*EF 11/06/22* (1)

# Work Order ID 71075

Tuesday, June 21, 2011 3:46:40 PM



Page 2

Item ID: D412-702-105B

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 6/21/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 6/21/2011 Req'd Qty: 1.00



Customer:

Reference: disassemble

Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Stop



Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

11/6/22  
MF  
11-06-22

# Picklist Print

Tuesday, June 21, 2011 3:46:37 PM

Page 1

Work Order ID: 71075

Parent Item: D412-702-105B

Parent Item Name: Harness Assembly



Start Date: 6/21/2011

Required Date: 6/21/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev A 07.05.10 new issue EC  
IPP Rev:B Removed Decal D3569 07-07-06 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3573-1 		Manufactured	No				Each	0.0000		-1			
Adapter D3579-046 		Manufactured	No				Each	3.0000		-1			
Shoulder Harness													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				ST273		3						59040	
				65014		3							
D412-702-105B 		Manufactured	No				Each	0.0000		1			
Harness Assembly													

65012

EP 11/06/22

EP 11/06/22

59040

EP 11/6/22

Status	Item ID	Rev	Name	Quantity Per	UOM	Stop Date	Route Seq ID	Scrap %	rap Quant	Comments	Date Last Mod
✓	AN960JD10LL		Washer	4.0000	Each			0 %	0.0000		6/24/2009 5:48...
✓	D3573-1		Adapter	1.0000	Each			0 %	0.0000		12/5/2009 7:00...
✓	D3579-046		Shoulder Har...	1.0000	Each			0 %	0.0000		4/26/2011 8:16...
✓	K62		CLIP	1.0000	Each			0 %	0.0000		6/24/2009 5:48...
✓	MS21042L3		Nut	4.0000	Each			0 %	0.0000		6/24/2009 5:48...
✓	MS24693-S273		Screw	4.0000	Each			0 %	0.0000		6/24/2009 5:48...

65d2

-105 B

71075

# Picklist Print

Wednesday, January 05, 2011 1:27:41 PM

Page 1

Work Order ID: 65012

Parent Item: D412-702-105B

Parent Item Name: Harness Assembly



Start Date: 1/5/2011

Required Date: 1/14/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev A 07.05.10 new issue EC  
IPP Rev:B Removed Decal D3569 07-07-06 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN960JD10LL  Washer		Purchased	No				Each	4,051.000	4	4			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					
				ST349			4051						
				19085			472						
				19600			3579						
D3573-1  Adapter		Manufactured	No				Each	9.0000	1	1			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					
				ST244			9						
				45926			1						
				55680			1						
				57222			7						
D3579-046  Shoulder Harness		Manufactured	No				Each	2.0000	1	1			
				<u>Location</u>			<u>Loc Qty</u>	<u>Loc Code</u>					
				ST273			2						
				59040			2						

*EPB 11/01/06*

*EPB 11/01/06*

*EPB 11/01/06*

# Picklist Print

Wednesday, January 05, 2011 1:27:41 PM

Page 2

Work Order ID: 65012

Parent Item: D412-702-105B

Parent Item Name: Harness Assembly

Start Date: 1/5/2011

Required Date: 1/14/2011

Start Qty: 1.00

Required Qty: 1.00

K62

Purchased

No

Each

21.0000

1

1



CLIP

Location

Loc Qty

Loc Code

ST243A

21

110957

1

113878

20

Each

1,746.000

4

4

MS21042L3

Purchased

No



Nut

Location

Loc Qty

Loc Code

ST300

1746

114784

9

115835

833

116373

4

116391

900

Each

788.0000

4

4

MS24693-S273

Purchased

No



Screw

Location

Loc Qty

Loc Code

ST288

788

100151

788

Wednesday, January 05, 2011 1:27:41 PM

Shop Packet Print

Page 2